

## Step 1:

Roll the front of the machine tracks on street plates or matting in soft soil conditions.

### Step 2:

Hook inner lift eyes of panel with supplied pulling cables.



### Step 3:

Back fill no more than 2' or follow backfill requirements of project details. **DO NOT** compact soil against slide rail panels.

### Step 4:

Shock load cables by pulling on panel until knife edge of inner panel is exposed.



#### Step 5:

Repeat *Step 3* until panel is pulled to upper or middle panel, then remove fully.



Step 6:

All inner panels should be removed before upper panels.

## Step 7:

Backfill and remove all upper panels.



# Step 8:

Push/ pull top of posts with machine bucket. **DO NOT** pull on channel.

# Step 9:

Static pull posts from ground.



### Step 10:

Remove all soil debris from tracks of post. A small spade shovel or breaker bar is suggested.